This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

APPLN. FILING DATE: NOVEMBER 25, 2003
TITLE: ENTRAPED DETECTING DEVICE FOR

OPENING-CLOSING MEMBER INVENTOR(S): SHINTARO SUZUKI ATTORNEY DOCKET NO: 000409-069

SHEET 1 of 5

vectables expensive that the




FIG. 1

1

WISIN CIXIN 保び草


2003#11#25B 15:31

APPLN. FILING DATE: NOVEMBER 25, 2003
TITLE: ENTRAPED DETECTING DEVICE FOR

OPENING-CLOSING MEMBER INVENTOR(S): SHINTARO SUZUKI ATTORNEY DOCKET NO: 000409-069

SHEET 2 of 5

(PRODUCE LEED TO PROPERTY LEED.



APPLN. FILING DATE: NOVEMBER 25, 2003


TITLE: ENTRAPED DETECTING DEVICE FOR

OPENING-CLOSING MEMBER INVENTOR(S): SHINTARO SUZUKI ATTORNEY DOCKET NO: 000409-069


SHEET 3 of 5

PARTITION OF THE PARTIT

F I G. 3



F I G. 4




APPLN. FILING DATE: NOVEMBER 25, 2003
TITLE: ENTRAPED DETECTING DEVICE FOR

OPENING-CLOSING MEMBER INVENTOR(S): SHINTARO SUZUKI ATTORNEY DOCKET NO: 000409-069


SHEET 4 of 5

Productive Commence

F I G. 5



F I G. 6




APPLN. FILING DATE: NOVEMBER 25, 2003

TITLE: ENTRAPED DETECTING DEVICE FOR

OPENING-CLOSING MEMBER INVENTOR(S): SHINTARO SUZUKI ATTORNEY DOCKET NO: 000409-069

SHEET 5 of 5

F I G. 7



F I G. 8

